

Threading Wood for Machine Screws

Cut durable threads in wood with metal taps

by Pat Warner

Machine screws make excellent joints in wood. They are hard to break, and some of the head configurations are quite decorative. I use them for knockdown furniture joints and for adjustable jigs that need to be strong. But machine screws are not as simple to use as wood screws because they don't cut their own threads the way wood screws do.

The most common solution is a threaded insert (for more on this, see *FWW* #120, pp. 79-81). But I've found you really don't need inserts to make strong joints with machine screws. Metal taps will cut crisp, strong and durable threads in any hardwood. It takes about the same amount of force to strip wood threads as it does to pull a threaded insert out of its hole. And if you tap the wood deeper than a threaded insert requires, the wood joint will be stronger. Machine screws in an inch of wood threads

will make a really tough knockdown joint.

Wood threads require careful drilling and tapping. The wrong size drill bit or a misaligned hole will lead to a weak connection. But by following the drilling schedule at right and using the proper tools, you can produce deep, crisp and strong threads without too much trouble.


The only specialized tools that you will need are taps. I have taps in four screw sizes: $\frac{3}{8}$ -16, $\frac{5}{16}$ -18, $\frac{1}{4}$ -20 and #10-24 (the first number is the diameter of the screw; the second is the number of threads per inch). You will also need drill bits, transfer punches and countersinks.

The pilot holes need to be drilled first to locate the thread holes properly. The machine screw should slide easily through the pilot hole, just as a wood screw should. If the head configuration calls for it, I would countersink the pilot holes for the screw heads at this point.

Clamp the piece with the pilot holes to the piece that receives the threads, and transfer the hole locations. I use a transfer punch the same size as the pilot hole, drilling the thread holes on the punch marks. Chamfer the mouth of the thread holes about $\frac{1}{32}$ in. greater than the tap diameter. If you don't, the tap may tear out the surface grain when you cut the threads.

I have tried tapping by hand with a wrench, but I just can't tap straight. A drill press will give you excellent results safely every time. Just don't turn on the drill press. In fact, unplug the machine before starting this procedure.

Clamp the work firmly, and put the tap in the chuck. Turn the drive pulley by hand while guiding the tap into the thread hole with the quill feed. Once you've started the threads, you can tap the rest by hand if you like. □



Tooling to cut threads for $\frac{5}{16}$ -18 machine screws

Pilot hole

$\frac{5}{16}$ -in. drill bit for pilot hole



$\frac{5}{16}$ -in. countersink



Threaded hole

$\frac{5}{16}$ -in. transfer punch to locate thread hole



$\frac{1}{4}$ -in. drill bit for thread hole



$\frac{1}{4}$ -in. countersink



$\frac{5}{16}$ -18 tap for thread hole

